



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining
JOHN R. BAZA
Division Director

Minerals Inspection Report

Reviewed PTB

Report Date: **03/31/2014**

Mine Name: Weston #1	Permit Number: S/007/0039	Mine Status: Active
Operator Name: Quality Building Stone	Inspection Date: 03/26/2014	Permit Fees: Paid
Inspector(s): Wayne Western	Inspection Time: 6:00 - 6:30 PM	Bond Amount: \$13,300
Attendee(s): none	Weather: Cold mostly clear	Bond Escalation: 12/31/2010
Inspection Purpose: Routine inspection		Prior Inspection: 04/04/2013

Conclusions and Recommendations

Elements of Inspection	Evaluated & Commented	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input type="checkbox"/>
The Operator submitted permit fees but not annual reports. Bond was due for escalation in 2010. The Division is working with the Operator to increase bond for this and other sites. There was some new disturbance and the site.		
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Access to the site is block to help prevent public access.		
3. Protection of Drainages/Erosion Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Disturbed area was pocked		
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>

Inspector's Signature: Wayne Western

CC:

File: /nrwogmfs1/OGM/GROUPS/MINERALS/WP/M007-Carbon/S0070039-Weston1/inspections/INSP03262014.pdf



Entrance to the site



Evidence of recent blasting activities



Recently disturbed site



Upper Area